

ENGINEERING DEPARTMENT  
*Town of Poughkeepsie*

**PETER D. SETARO, P. E.**

Town Engineer

**DONALD A. BEER**

Associate Town Engineer

**SEAN CRIMMINS**

Assistant Town Engineer

**PETER HOBDAV**

Assistant Town Engineer

ONE OVEROCKER ROAD  
POUGHKEEPSIE, NY 12603

TEL # (845) 790-4736

TEL # (845) 790-4748

TEL # (845) 790-4747

**TOWN OF POUGHKEEPSIE  
CIPP SANITARY SEWER PIPE SPOT REPAIRS - 2018  
POUGHKEEPSIE, NEW YORK**

**CONTRACT 2018-06**

Addendum No. 1  
August 27, 2018

Page 1 of 2

This addendum is issued for the above mentioned contract.

1. Many of the suggested CIPP Point Repairs indicate IR (infiltration runner) or IJ (infiltration at joint). In most cases, running infiltration requires grouting the leak prior to installing CIPP point repairs. How would we be compensated for a grout crew, equipment and grout?
  - a. The CIPP Point repair would need to be the type that seals the interior of the pipe to make it watertight.
2. If MB (major breaks) or other specified defect cannot be repaired by trenchless methods, how do we get compensated for time it takes to flush and inspecting the line?
  - a. If there is a concern in regard to a Major Break, the provided videos and reports should be reviewed before attempting the repair. If it is determined that the repair should not be attempted, another location will be provided.
3. There is no item for maintenance of traffic or police details. If police are required, will the cost be paid by the Township?
  - a. This should be covered under the mobilization line item. It is recommended to review the streets and repair locations with the provided maps to determine the magnitude of traffic protection needed.

## CONTRACT 2018-06

Addendum No. 1  
August 27, 2018

Page 2 of 2

4. Water will be required for flushing. Will the Township supply water?
  - a. Yes.
  
5. There is no item for re-instating laterals. Would the Township consider adding an item for service laterals?
  - a. The spot repairs should not require reinstating laterals. If a repair is made in the wrong location and covers a service lateral, the contractor is responsible to reinstate it. If there is a concern in regard to the location of a service lateral in relation to the spot repair, another repair location will be provided.
  
6. If extra material is required to span a fracture/crack, over the 4' length, how would the contractor be compensated?
  - a. If additional material is required to span over a crack, it would be considered an additional repair and will be compensated with the "additional allowance" line item.
  
7. Would the Township consider adding a "per foot" item for any length over 4' length?
  - a. There is not enough time to modify the contract, additional material can be compensated with the "additional allowance" line item.