

**Pipe Graphic Report of
Database: POUGHKEEPSIE.mdb**

PO #

Sheet # 180
Surveyor RICH (06022759)
Street MILL BANK ROAD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20150310 12:38
Drainage

Upstream MH3	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft
Downstream MH34	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft

Use	Direction Upstream	Joint Length	Height 8 in	Width
Shape Circular	Flow Control	Total Length	Year Laid	
Material Asbestos Cement	Pre Cleaning Jetting	Surveyed 283.1 ft	Year Rehab	
Lining	Weather	Purpose		
Location		Category		


Media/Tape #		Pressure
Northing	Easting	Elevation
GPS Accuracy	Coordinate System	

Additional Info

Work Order

Project

DVS File C:\ Documents and Settings\ User\ My Documents\ My Muni Data\ POUGHKEEPSIE\
MH3_MH34_150310_180.wmv



Pipe Graphic Report of
Database: POUGHKEEPSIE.mdb

PO #

Sheet # 180
Surveyor RICH (06022759)
Street MILL BANK ROAD
City POUGHKEEPSIE
Further Loc. Details

Owner

Date 20150310 12:38
Drainage

Upstream MH3	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft
Downstream MH34	Rim-Invert 0.0 ft	Grade-Invert 0.0 ft	Rim-Grade 0.0 ft

Use	Direction Upstream	Joint Length	Height 8 in	Width
Shape Circular	Flow Control	Total Length	Year Laid	
Material Asbestos Cement	Pre Cleaning Jetting	Surveyed 283.1 ft	Year Rehab	
Lining	Weather	Purpose		
Location		Category		

Media/Tape #	Easting	Elevation	Pressure
Northing	Coordinate System		
GPS Accuracy			

Additional Info

Work Order

Project

DVS File C:\ Documents and Settings\ User\ My Documents\ My Muni Data\ POUGHKEEPSIE\
 MH3_MH34_150310_180.wmv

